


1/12

FIG. 1



2/12

FIG.2




FIG.3

POWER SAVING MODE	RETURN TIME
a	0
b	1
c	3

3/12

FIG.4





FIG.6

JOB TO BE EXECUTED	DIFFERENCE TIME
A	5
B	1
C	15
D	3
E	5

10030270.010202

4/12

FIG.5




10030270.010202

202010" 0/20E00T

10/030270

5/12

FIG.7



6/12

FIG.8






FIG.9



8/12

FIG. 10



10030270.010202



10/030270

COLON ET AL (783) 413-3000

DOCKET # 24764808 SHEET 9 OF 12


9/12

FIG.11

JOB TO BE EXECUTED	DIFFERENCE TIME	PERMITTED ERROR TIME
A	5	2
B	1	4
C	15	0
D	3	4
E	5	4


10/12

FIG.12



11/12

FIG.13



202070-020E001

12/12

FIG.14

(a)

C	→	POWER SAVING MODE	RETURN TIME
6		A	5
4		B	16
		D	3
		E	5

(b)

POWER SAVING MODE	RETURN TIME	4
A	5	
B	1	
C	15	
D	3	
E	5	

(c)

POWER SAVING MODE	RETURN TIME
A	5
B, C	16
D	3
E	5